



NOTE:
 STANDOFF BRACKET LOCATIONS
 ARE $\pm 1"$.
 DO NOT PREDRILL HOLES IN THE
 STRUCTURE.
 HOLES SHOULD BE MATCH DRILLED
 TO INSURE PROPER ALIGNMENT



DRAWN GB	4/27/2012	 130 Seltzer Road, Crosswell, Michigan, U.S.A., 48422	
CHECKED			
APPROVED		TITLE	
PART D0570353 F25W FOR CATALOG		F25W	
THIS PRINT IS PROPERTY OF COTTERMAN® CO., AND MAY NOT BE USED IN WHOLE OR PART WITHOUT WRITTEN PERMISSION.		Drawing is computer generated, and print might not be to scale	
SIZE C	DWG NO D0570353 F25W FOR CATALOG.dwg	REV A	
QUOTE			SHEET 1 OF 1